



Meridian Audio Limited
Latham Road, Huntingdon
Cambridgeshire PE29 6YE
United Kingdom


T +44(0)1480 445678
F +44(0)1480 445686
E info@meridian.co.uk
www.meridian-audio.com

Technical Note TN34

23rd November 2010

557 OP40 Replacement with OPA134

557 Modification for Replacing OP44 (needs to be done for both channels)



Connect pin 7 to pin 4 with a 27K resistor