

MERIDIAN TECHNICAL NEWS

TO WHOM IT MAY CONCERN

222 CONTROL BOX

We have noticed in a few installations interference sensitivity on the 222 which can lead to the product re-setting at random times. There is a simple cure available which involves fitting a capacitor of between 10n and 100n between pins 4 and 5 of the power supply supervisory chip U111 type TL 7705A. This chip is socketed and the capacitor can either be fitted to the underside of the PCB by a service engineer or we will supply, on request, exchange ICs with the capacitor already fitted.

J.R. Stuart
Technical Director



7th April, 1989

BOOTHROYD STUART LTD

13 Clifton Road, Huntingdon
Cambs PE18 7EJ, England
Telephone Huntingdon (0480) 52144
Telex 32577 (MERIDN)
Fax (0480) 59934

Contact Bob Stuart, Technical Director