



Meridian A500 Crossover (v1.0 14/02/94)



N.B. The circuit diagram has been taken from a PCB diagram. Applying normal crossover design principles shows that the tweeter is connected out of phase in this diagram. This may have been rectified with the actual internal wiring of the A500.